



B



D

E

A

B

C

D

E

Technical drawing of a stepped shaft. The shaft has a total length of 100 mm and a diameter of 10 mm. It features a step with a width of 20 mm and a diameter of 6 mm. The drawing includes dimension lines and tolerances: $0,6 \pm 0,05$ for the step width and $0,6_{-0,025}$ for the step diameter.

F

A line graph showing the relationship between Temperature [°C] on the x-axis and Electrical Load [A] on the y-axis. The x-axis ranges from 0 to 120 with major ticks every 20 units. The y-axis ranges from 0 to 2.0 with major ticks every 0.5 units. A smooth curve starts at (20, 2.0) and decreases as temperature increases, reaching 0 A at approximately 125°C.

Temperature [°C]	Electrical Load [A]
20	2.0
40	1.8
60	1.55
80	1.3
100	1.0
120	0.5
125	0.0

Control and test procedures according to DIN IEC 60512-5



All rights reserved

Department EL PD

Title	DIN Signal male connector straight
-------	------------------------------------

Inspected by
TADJE

Standardisation
HOFFMANN

Date
2019-06-13

State
Final Release

Doc-Key / ECM-Nr.
00560208/UGD/001/D
00000153444

Rev. D

A3